



CTU in Prague
Faculty of Civil Engineering
Department of Building Structures



Restoration of vaults

Šlechta restaurant in Prague - Bubeneč (Main Hall)

Presentation was created with the kind support of Ministry of Education Grant FRVŠ
2960/2011.


Description of the object

- ▶ Historical views on Šlechta restaurant



Description of the object

- ▶ truss above the main hall
 - ▶ New-made King Post Truss above the main hall
 - ▶ supported by circuit reinforced concrete rims and arch reinforced concrete ribs
 - ▶ full frames – King Post Truss with 2 purlins




History of the object

- ▶ construction time(1688 – 1693) – scale variant of Sternberg villa in Troy
- ▶ author – J. B. Matheym?? (same form as Sternberg villa)
- ▶ double-aisle building
- ▶ main hall was connected to a side halls by door openings (doors bricked before r.1725)
- ▶ in 1726 construction works caused by poor condition of the truss and roof (S. Löffler)
- ▶ in 1792 new ground floor hall was built on the west side
- ▶ in 1808 adapted into a restaurant
- ▶ in 1855 decided on reconstruction and extension of the terrace with veranda (B. Grueber)


History of the object

- ▶ the conversion of the early Baroque facade to the Gothicism facade
- ▶ made extension of both side-wings to the two storeys




History of the object

- ▶ Current state of Šlechta restaurant
 - ▶ waiting for the start reconstruction of Šlechta restaurant
 - ▶ there are static securing needed in the context of the construction of the tunnel Blanka



History of the object

- ▶ Current state of Šlechta restaurant




KRÁLOVSKÁ DVORANA
(ŠLECHTOVA RESTAURACE)
PRAHA 7 - BUBENEČ č.p. 20
ZAJIŠTĚNÍ PŘED RAŽBOU TUNELŮ

LEGENDA:

- PŮVODNÍ BAROKNÍ ZDIVO Z ROKU 1693
- NOVOGOTICKÁ PŘÍSTAVBA Z ROKU 1857
- BOURÁNÍ
- NOVÉ KONSTRUKCE
- OCELOVÁ ZTUŽUJÍCÍ TÁHLA

Description of defects

- ▶ Brick vault above the main hall
 - ▶ in the arch abutment at the northern perimeter wall crack exists (large horizontal reactions and insufficient rigidity in the imposition on the wall)



Analysis of defects


- ▶ Brick vault above the main hall
 - ▶ large horizontal reaction and insufficient rigidity in the imposition on the masonry caused cracks in the arch abutment at the northern perimeter wall

Restoration of defects

- ▶ The vault is sufficiently bearable to buckling
 - ▶ => steel rods will be made visibly under a listed fresco and after finalization of the tunnel will be removed)
 - ▶ => Reinforced concrete grid above the vault will be made
 - ▶ peripheral ring of reinforced concrete closed together with arch ribs(1 longitudinal, 3 transverse ribs)


Restoration of defects

- Brick vault above the main hall – grid construction of reinforced concrete





Restoration of defects

- ▶ Brick vault above the main hall - truss



Restoration of defects

- ▶ Alternative Option 2: Hanging damaged vault to masonry by reinforced concrete shell and steel draw rods
 - ▶ for significantly damaged vaults, reconstructed greater load than before reconstruction
 - ▶ shell – 60 mm concrete slab with KARL net
 - ▶ tied together with brick vault
 - ▶ steel pins
 - ▶ shell secured by draw rods with rectification
- 




Restoration of defects

- ▶ Alternative Option 2: Hanging damaged vault to masonry by reinforced concrete shell and steel draw rods
 - ▶ shear forces in the area of anchorage partially eliminated by reinforced concrete floor slab and rim

Restoration of defects

- ▶ Alternative Option 2: Hanging damaged vault to steel beam by draw rods
 - ▶ for significantly damaged vaults, reconstructed greater load than before reconstruction
 - ▶ reverse shell thickness approximately 60 mm, tied together with vault by pins (by 250 mm)
 - ▶ steel rod connecting the shell with steel profile



Restoration of defects

- ▶ Alternative Option 2: Hanging damaged vault to steel beam by draw rods
 - ▶ draw rods with rectification
 - ▶ => steel beam is a tension member, situated on the reinforced concrete rim
 - ▶ the masonry must be reinforced by grouting