



CTU in Prague
Faculty of Civil Engineering
Department of Building Structures


Restoration of truss

Church of St. Vaclav in Mikulovice

Presentation was created with the kind support of Ministry of Education Grant FRVŠ
2960/2011.


Description of the object

- ▶ view on church



Description of the object

- ▶ Truss - status before reconstruction
 - ▶ reconstruction time of truss- from 1768 to 1769
 - ▶ hip roof, king post truss with top purlin and suspension trusses
 - ▶ 5 full frames, between them are always 3 yeast frames
 - ▶ longitudinal bracing is reinforced by diagonal braces between threshold and top purlins




Description of the object

- ▶ longitudinal bracing




History of the object

- ▶ built probably before 1387 on the Mikulovice marl hill (275 m above sea level) on the former pagan grove, dominates the entire
- ▶ according to drawing from 1724 was church in that time still in Gothic style - single aisle with polygonal presbytery without external supporting pillars




History of the object

- ▶ 1750-52 placed the foundation stone of masonry bell tower adjoining to the western facade of the church
- ▶ simultaneously with the construction of the tower was made the total reconstruction of the entire Western frontage, in 1769 reconstruction completed
- ▶ current appearance of the church (baroque style), with newly built stone aisle, dates from 1768-69
- ▶ on the chancel plaster - paintings by Josef and Vaclav Kramolín of 1790
- ▶ since 2004 a total reconstruction of the church



History of the object

- ▶ ground plan of the church



History of the object

- ▶ 1885 solved static failure of the truss and floor
 - ▶ hanging tie beams by medium threshold purlin
 - ▶ added braces in full frames, which deal with tie beam deflection in their centers



History of the object

- ▶ Hanging tie beams by medium threshold purlin



- ▶ Suspension truss with medium threshold purlin



Description of defects

- ▶ Fault manifested on the the truss ridge of the roof



- ▶ Tie beams gridiron is severely damaged or completely missing. Yeast frames were unable to carry the load and there was a rapture of short exchanges

Description of defects

- ▶ Rapture of exchanges



Description of defects

- ▶ Some tie beams are in very poor condition and will require their total replacement




Description of defects

- ▶ Missing tie beams gridirons



Description of defects

- ▶ Because of vault, truss over the chancel is solved without tie beams - vault has no signs of damage



Description of defects

- ▶ Faults of other parts of the church
 - ▶ rapture of short exchanges led to cracks in the perimeter wall moldings, sometimes missing bricks



Description of defects

- ▶ Faults of other parts of the church
 - ▶ blown and weathered facade
 - ▶ cracked stone elements



Restoration of defects

- ▶ Securing construction by steel draw rods
 - ▶ secure the stability the truss
 - ▶ replacement of wooden truss elements
 - ▶ fungicidal treatment of the truss
 - ▶ the roof deck replacement



Restoration of defects



Restoration of defects

- ▶ condition after reconstruction



Restoration of defects

- ▶ construction of the tower roof



Restoration of defects

- ▶ condition after reconstruction

